

FIG. 1




FIG. 2

+

2/12




FIG. 2A




FIG. 3




FIG. 4

+

+

3/12




FIG. 5




FIG. 6




FIG. 7

+

+

4/12




FIG. 8






FIG. 9

+

5/12



+

6/12




FIG. 12




FIG. 13

+

+



7/12

EFFECT OF CABLE CURVATURE ON CABLE POSITION, 5 FT. EXACT DEPTH




FIG. 14




FIG. 15

+

8/12




FIG. 16




FIG. 17



9/12




FIG. 18




FIG. 19

+

10/12




FIG.20




FIG.21

+

11/12

DEPTH MEASUREMENT ERRORS NEAR CABLE BEND, 5 FT. CABLE DEPTH




FIG. 22

DEPTH MEASUREMENT ERRORS NEAR CABLE BEND, 5 FT. CABLE DEPTH




FIG. 23

+

12/12



CABLE DEPTH FROM 2-POINT HEIGHT MEASUREMENTS, 5 FT. DEPTH




FIG. 24

DEPTH ERROR DUE TO A FLUX MEASUREMENT ERROR OF 2%




FIG. 25

+